


Pioneer 1000

Replacement Parts List: Glass Windshield

Part Number OSU85-HL4-105

8/5/2019



No.	Description	P/N	Req'd Qty	Pkg Qty
A	Glass and Gasket only	OSU85-HL4-105R1	1	See desc.
B	(4 ea) Push Darts & Push Nuts	OSR71-HL4-A00R9	1	See desc.
1	Windshield Assy.	Not available		
2	Cam lock	OSR85-HL4-101R1	4	1
3	Left gasket	OSR71-HL4-A00R10	1	1
4	Right gasket	OSR71-HL4-A00R11	1	1
5	Push dart	OSR71-HL4-A00R9	4	See B
6	Push nut	OSR71-HL4-A00R9	4	See B
7	6 x 18 mm screw	OSU95-HL4-10R6	9	10
8	Flat washer	OSU95-HL4-10R3	9	10
9	Trim clip	OSU95-HL4-10R20	2	10
10	Center support bracket	OSR71-HL4-A00R12	1	1