

# Detail

2017 HONDA SXS500M2 Pioneer 500 - Base

Color:RED

Keyboard:KEY #40

VIN/Serial No:1HFVE0309H4203904

Plate:

Odom/Hrs In:87

Out:89

**DIAG**

**Description:** CUSTOMER STATES PIONEER IS STUCK IN GEAR, HIS GRANDDAUGHTER WAS RIDING IT AROUND AND SAID IT WAS STUCK IN 2ND GEAR AND WOULDN'T SHIFT. I EXPLAINED TO CUSTOMER THAT IS A CHARACTERISTIC OF THESE 500'S. BEFORE PIONEER DIED IT WOULDN'T EVEN "TRY TO TURN OVER" . NOW UNIT IS DEAD/UNABLE TO LOG HOURS.

**Resolution:** Battery is discharged. Pulled to charge and check. Installed test battery and drove unit. Unit seems to be shifting and driving as it should. Will continue to drive after battery diag. Service light is on (25hr). 7/17/19  
 Battery charged up okay. Charging system is okay (14.7 v) 7/18/19  
 Pulled and cleared codes:  
 23-1 Shift Spindle Malfunction  
 57-1 Shifter Fail  
 64-1 Sub Power voltage low

**Recommend:**KEEP BATTERY ON A TRICKLE CHARGER WHEN STORED

**Labor**

Description	Technician	Hour	Total
DIAG	Jesse W. Benson	1	\$95.00
<b>Labor Subtotal</b>			<b>\$95.00</b>
<b>Job Subtotal</b>			<b>\$95.00</b>

<b>All Jobs Subtotal:</b>	<b>\$95.00</b>
<b>Shop Supplies:</b>	<b>\$4.75</b>
<b>Tax:</b>	<b>\$8.23</b>
<b>Total:</b>	<b>\$107.98</b>
<b>Less Deposits:</b>	<b>\$0.00</b>
<b>VISA:</b>	<b>(\$107.98)</b>
<b>Total Due:</b>	<b>\$0.00</b>